

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	外-3925	DATE	24, Jan, 2025
MANUFACTURE	Tesla, Inc. (Japanese Importer; Tesla Japan)		
DESCRIPTION OF DEFECT	<p>Due to inadequate software design for the warning display of the tire pressure monitoring device on the touch screen, the warning is not displayed for a while even if the faulty condition persists when the vehicle is started up after the vehicle has once entered the sleep mode.</p> <p>Therefore, the driver is not warned of the malfunction and the tire pressure monitoring device does not meet the criteria for a tire pressure monitoring device.</p>		

TYPE	NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-3L13T	Model 3	2024	12
ZAA-3L23T		2024	22
ZAA-3L24PT		2024	3
ZAA-YL1YT	Model Y	2024	17
ZAA-YL3YT		2024	8
ZAA-YL3YPT		2024	1
		TOTAL	63