

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	GAI 3934	DATE	21.Jan.2025
MANUFACTURE	BMW (Japanese Importer)		
DESCRIPTION OF DEFECT	Due to a programming error in a control unit, every engine start in the affected vehicles takes place in warm start mode (without preheating of the catalytic converter), regardless of the actual engine temperature/engine shutdown period. This leads to increased emissions during the warm-up phase when the engine is cold.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-R127A	「R12 nineT」	2024	45
8BL-R127A	「R12」	2024	25
		2024	70