

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3941	DATE	2025/2/13
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan G.K.)		
DESCRIPTION OF DEFECT	<p>On certain V-Class (447 platform) with 4-cylinder diesel engine the engine control unit software might not meet specifications.</p> <p>In case of an asymmetric heating of an aged differential pressure sensor, the functional monitoring of the sensor might erroneously detect a defect in the differential pressure sensor, although there is no defect present. As a result, the limp home mode would be activated and, after three fault detections, the malfunction indicator light would be illuminated.</p> <p>As a result, local legal requirements regarding exhaust emissions and OBD monitoring might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-447815	V 220d	2016	486
LDA-447811			5,948
-447811C-		2019	3
3DA-447815C			198
3DA-447811C			2,212
		TOTAL	8,847