

**Form No. 4: Summary of Recall Campaign in English (Related to Article 2)**

**Vehicle Safety/Pollution Recall Campaign in Japan**

Import Vehicles

Campaign No.	Gai-3939	Date	Feb. 4, 2025
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	<p>The incorrect specification plastic housing will, over time and with vehicle use, crack allowing oil to leak out onto the engine and into the engine bay. An oil leak under pressure in this area could result in oil coming into contact with hot components on the engine which may result in a fire.</p> <p>Vehicles will have the oil filter housing, complete with filter and associated O-rings, replaced.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
3CA-L123WA	Range Rover Sport	2023 - 2024	3
3CA-LE72WAB	DEFENDER	2023	2
3CA-LK93WA	Range Rover	2023	2
3CA-LW3WHE	Range Rover Sport	2022	1
		2022 - 2024	8

(JIS A4 size)