

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	Gai-3930	DATE	February 6, 2025
MANUFACTURER	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	Due to an inappropriate structure of the fuel hose clip in the engine compartment, the fuel hose and the hose clip may rub against each other due to vibrations while driving. If the vehicle is continued to be used in this condition, the fuel hose may wear out, and in the worst case, the hose may develop a hole, causing a fuel leak and a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7AA- LJLH5HH	ARKANA	2022 - 2023	413
		TOTAL	413