

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-3924	DATE	28 <sup>th</sup> Mar, 2025
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Regarding the CCU (Combined Charging Unit) water jacket, it was found that during the production process of the water jacket a possible casting fault might have caused porosities within the jacket located at the screw holes for a specific production batch. In rare cases these porosities might lead to a leakage allowing coolant to spread on the circuit board and possibly cause a short circuit. it may trigger the warning lamp and happen the e-train power off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-42AW44	「BMW i4 eDrive35」	2023	15
ZAA-72AW44	「BMW i4 eDrive40」	2023	24
ZAA-32AW89	「BMW i4 M50」	2023	5
ZAA-52EJ89	「BMW i7 xDrive60」	2023	19
ZAA-22CF89A	「BMW iX xDrive50」	2023	18
ZAA-62EF67	「BMW iX1 xDrive30」	2023	55
ZAA-42DU44	「BMW iX3 M Sport」	2023	26