

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3972	DATE	27th March 2025
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K.)		
DESCRIPTION OF DEFECT	The wires in the connector system may form a bridge if they are exposed to a combination of different factors, such as high temperatures, heavy current loads, and excessive lateral pulling on the wiring. If the connector blades bridge, it poses a potential risk of reaching a thermal threshold beyond the connector system's capacity, leading to deformation of the connector. This may ultimately cause damage to the bike and increase the risk of a crash.		

2BL-DGJ900	Bonnaville T100	2021 - 2022	252
	Street Twin	2020 - 2022	352
	Street Scrambler	2021 - 2022	267
2BL-DHJ1200	Bonneville T120	2020 - 2021	63
8BL-DGJ900	Bonnaville T100	2022 - 2023	387
	Speed Twin 900	2022 - 2023	862
	Scrambler 900	2022 - 2023	285
8BL-DHJ1200	Bonneville T120	2021- 2023	1467
		TOTAL	3935