

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-3961	DATE	Mar. 19th, 2024
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	Due to inappropriate conditions of the motor sensor circuit board in the production process and insufficient design consideration of the contact pin length, there is a possibility that signal interference in the electronics of the brake system may occur. In this case, the brake warning lights lighting up and check control message will be displayed. Also, an unexpected loss of hydraulic brake assist may occur and may result in an extended braking distance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7AA-42EM	XB7	2023-2025	22
TOTAL			22