## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIGN No.	GAI-3967	DATE	March 19, 2025	
MANUFACTURER	Audi			
WANDFACTURER	(Japanese Import	Importer: VOLKSWAGEN Group	Japan K.K.)	
DESCRIPTION OF DEFECT	Due to insufficient software program design verification in the development			
	of ABS control unit, the electronic parking brake may not function correctly			
	under certain circumstances. The "N" gear position may not be shown in the			
	instrument cluster when it should be displayed. As such, there is a risk of the			
	vehicle roll away while parked. In addition, the "P" gear position is still			
	displayed when the gear is "N", which fail to comply with the requirements of			
	Safety Regulations for Road Vehicles.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-FZEBJ	Audi Q4 40 e-tron	2022-2023	890
		Total	890