

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-3954	DATE	14. 03. 2025
MANUFACTURER	Royal Enfield (A unit of Eicher Motors Ltd.) (Japanese Importer : PCI.co.Ltd)		
DESCRIPTION OF DEFECT	In some side reflectors, the internal surfaces of the reflectors are not properly molded due to improper equipment management. Therefore, there is a risk that the reflected light will be scattered and it will not comply of the Safety Standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ME3ELJ15	CLASSIC 350	2023	162 units
ME3ERJ15	HUNTER 350	2023	430 units
8BL-DJER	HUNTER 350	2023	1 unit
ME3ESP15	SUPER METEOR 650	2023	1 unit
		TOTAL	594 units