

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-3955	DATE	14. 03. 2025
MANUFACTURER	Royal Enfield (A unit of Eicher Motors Ltd.) (Japanese Importer : PCI.co.Ltd)		
DESCRIPTION OF DEFECT	In some side reflectors and rear reflectors, the internal surfaces of the reflectors are not properly molded due to improper equipment management. Therefore, there is a risk that the reflected light will be scattered and it will not comply of the Safety Standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ME3EMJ15	METEOR 350	2023	244 units
8BL-DJEM	METEOR 350	2023	1 unit
ME3EGP15	CONTINENTAL GT 650	2023	9 units
ME3EHP15	INT 650	2023	9 units
		TOTAL	263 units