

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

|                       |  |      |                 |
|-----------------------|--|------|-----------------|
| CAMPAIGN No.          | GAI-3963   | DATE | March. 14. 2025 |
| MANUFACTURER          | HONDA AUTOMOBILE(THAILAND)CO., LTD.<br>HONDA MOTOR CO., LTD.   |      |                 |
| DESCRIPTION OF DEFECT | The Automatic Collision Notification system does not automatically reconnect after the connection is interrupted due to being out of the service area during the call connection because the control program of the telematics control unit is inappropriate. Therefore, it does not comply with safety standards. |      |                 |

| TYPE    | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------|-----------------|---------------------|-------------------|
| 6AA-CY2 | 「ACCORD」        | 2024～2025           | 3,092             |
|         |                 | TOTAL               | 3,092             |

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

| PARTS                   | PART No.      | DELIVERED AS “SERVICE PARTS” | NUMBER OF PARTS |
|-------------------------|---------------|------------------------------|-----------------|
| TELEMATICS CONTROL UNIT | 8B110-30A-J52 | 2024                         | 7               |
|                         |               | TOTAL                        | 7               |