

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3964	DATE	March. 14. 2025
MANUFACTURER	HONDA AUTOMOBILE(THAILAND)CO., LTD. HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Due to an inappropriate control program for the parking pilot* parking assistance system, if the relevant function is used with the password input screen left shown on the display, the warning sound will not sound when steering assistance ends when parking or exiting. Therefore, it does not comply with safety standards. * Supports parking by controlling steering, acceleration, and braking.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6AA-CY2	「ACCORD」	2024～2025	3,092
		TOTAL	3,092

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS	PART No.	DELIVERED AS “SERVICE PARTS”	NUMBER OF PARTS
INFOTAINMENT CONTROL BOX ASSY	8A501-30A-JA2	2024～2025	8
		TOTAL	8