

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-3919	DATE	10 th Mar, 2025
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Affected vehicles may be equipped with a double universal joint of the steering spindle in which the specification according to production may not have been appropriate for the application. Furthermore, these components may have experienced a pre-damage during assembling handling. A pre-damage in connection with the increased brittleness of the material due to the material change, certain steering movements may cause the swivel socket of the double universal joint to break. If the swivel socket is broken, this could be noticed due to unusual noises on the steering column and a faltering or indirect steering feel. In the worst case, higher steering forces must be applied unexpectedly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-22GW20	「BMW 523d xDrive」	2024	19
ZAA-82EH93	「BMW i7 M70 xDrive」	2024	1