

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3952	DATE	6, Mar, 2025
MANUFACTURER	Automobili Lamborghini SpA (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	The screws on the oil circuit connection flange from radiator to the oil tank may not have been properly torqued. Should the mounting assembly not meet the torque specification, the oil line could leak oil, which vapors could potentially contact hot components increasing the risk of a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7LA-ZMREV	REVUELTO	2024	1