

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	GAI 3944	DATE	3.Mar.2025
MANUFACTURE	BMW (Japanese Importer)		
DESCRIPTION OF DEFECT	BMW Motorrad has established that due to insufficient sealing of the control unit, moisture can penetrate the reverser control unit (optional equipment). This moisture, in conjunction with the permanent energization of the control unit over the duration, can lead to corrosion of electrical contacts inside the control unit. Corrosion can lead to malfunction of the control unit (failure of the reverser comfort function).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-R187A	BMW R18 Pure	2020 – 2021	410
2BL-R187A	BMW R18 Classic	2020 – 2021	174
8BL-R187A	BMW R18 Pure	2021 – 2024	275
8BL-R187A	BMW R18 Classic	2022 – 2024	225
8BL-R187A	BMW R18 B	2021 – 2024	233
8BL-R187A	BMW R18 Roctane	2023 – 2024	156
8BL-R187A	BMW R18 Transcontinental	2021 – 2024	211
		TOTAL	1,684