

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3983	DATE	24.04.2025
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to incorrect encoding data, the Welcome light overrides the parking light and all LEDs on the deactivated parking light side will light up for longer than 3 seconds before turning off again. As a result, the maximum time span until Welcome Light Animation defined in the Japanese Safety Regulation will be exceeded.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-12GA15	「MINI Countryman C」	2023 - 2024	356
3DA-62GA20	「MINI Countryman D」	2023 - 2024	1754
ZAA-42GA33	「MINI Countryman E」	2023 - 2024	178
3BA-22GA20	「MINI Countryman S ALL4」	2023 - 2024	763
ZAA-52GA67	「MINI Countryman SE ALL4」	2023 - 2024	201
7BA-32GA20	「MINI JCW Countryman ALL4」	2023 - 2024	606
		TOTAL	3,858