

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3986	DATE	April 22, 2025
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	In the software program of virtual cockpit instrument cluster, due to insufficient design study, the cable inside the virtual cockpit during the drive may result in the software detecting increased contact resistance and switching the display off. As such, the speedometer, total odometer, airbag warning etc. will not be displayed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-4MDCBA	Audi Q7 55Tq Air-suspension	2021	107
3AA-4MDCBS	Audi Q7 55Tq	2021	10
3AA-F1DCBA	Audi Q8 55Tq Air-suspension	2021	154
3AA-F1DCBS	Audi Q8 55Tq	2021	1
3AA-F1DHUA	Audi RSQ8	2021	82
3AA-F2DJPA	Audi RS7 SB Air-suspension	2021	38
3AA-F2DJPF	Audi RS6 Avant	2021	80
3AA-F2DJPL	Audi RS6 Avant Air-suspension	2021	46
3AA-F2DJPS	Audi RS7 SB	2021	64
3AA-F2DKMA	Audi S7 SB	2021	28
3AA-F2DKML	Audi S6	2021	92
3AA-F2DKNF	Audi A6 45Tq	2021	169
3AA-F2DKNS	Audi A7 SB 45Tq	2021	116
3AA-F2DLZF	Audi A6 55Tq	2021	27
3AA-F2DLZS	Audi A7 SB 55Tq	2021	40
3AA-F8CWWF	Audi S8	2021	54
3AA-F8CXYP	Audi A8 60Tq	2021	14
3AA-F8CXYP	Audi A8L 60Tq	2021	11
3AA-F8CZSF	Audi A8 55Tq	2021	121
3CA-F2DFBF	Audi A6 40TDIq	2021	284
3CA-F2DFBS	Audi A7 SB 40TDIq	2021	96
ABA-4MCYRA	Audi Q7 45Tq Air-suspension	2021	82
		Total	1,716