

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3988	DATE	April 22, 2025
MANUFACTURE	DS Automobiles (Japanese Importer :Stellantis Japan Ltd.)		
DESCRIPTION OF DEFECT	On the affected vehicles, the crimping of the rear axle adjustment rod on bushing was not according to specification. Instead of remaining in its original position, the tie toe moves on the bushing which may lead to knocking noise from rear, steering wheel misaligned or vehicle drift from its trajectory. In worst case scenario the customer may lose the control of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-X745G06H	「DS 7 CROSSBACK E-TENSE」	2022 - 2023	98
		TOTAL	98