

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3984	Date	April 17, 2025
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	On Polo vehicles of a limited production period the bolted connections of a drive shaft to the gearbox may not have been correctly carried out. A loose bolted connection usually leads to loss of drive when pulling away.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-AWDLA	Polo 1.0/70kW	2024	2
		Total	2