

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-3958	DATE	Apr. 16, 2025
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K.)		
DESCRIPTION OF DEFECT	The regulator output wire (red wire) may rub on the front corner of the crankcase. Over time, the wire insulation may wear, exposing the wire and potentially causing a short to ground.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-FL6	CVO ROAD GLIDE	2023	234
8BL-FL6	CVO STREET GLIDE	2023	156
		TOTAL	390