VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3981	DATE	15th April 2025	
MANUFACTURE	Triumph Motorcycles Limited			
	(Japanese Importer : Triumph Motorcyces Japan K.K.)			
DESCRIPTION OF DEFECT	Under certain tire service conditions (e.g., low inflation pressure, heavy load, road conditions, mileage			
	at almost the half of tire life, etc.), irregular tire wear may develop, which, over time, may result in			
	breakage of the zero-degree reinforcement. If this condition is not promptly detected, it may lead to			
	the partial detachment of the tread layer and/or a sudden loss of air pressure, which may result in			
	loss of control and an increased risk of a crash.			

8BL-PVJ1200	Tiger 1200 GT Pro	2022 - 2024	89
	Tiger 1200 GT explorer	2022 - 2024	49
		TOTAL	138