

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3975	DATE	10 April, 2025
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	For the right and left sides of seat belt buckles for rear seats, it is possible that they are fitted with the aluminum butyl sheets trapped due to inappropriate fitting work. Therefore, seat belt buckles may not be tightened properly and could be loose while in use of vehicle, in the worst case, it cannot ensure the performance of seat belts for passenger protection in vehicle collision.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-992PA1	911 Carrera	2024	4
3BA-992PA2	911 Targa 4		4
	911 Targa 4S		2
	911 Carrera 4		1
3BA-992PE	911 Turbo S		10
7BA-992NC1	911 Carrera T		6
	911 Carrera GTS		2
7BA-992NC2	911 Carrera 4 GTS		6
	911 Targa 4 GTS		3
		Total	38