

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	Gai-3995	DATE	May 22, 2025
MANUFACTURER	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	In the fuel injection system, the plating process for the injector rail was inappropriate, so the plating may peel off during use. As a result, the peeled plating may clog the injector, causing the air-fuel ratio to deteriorate and the warning light to come on. If the engine is continued to be used in this condition, there is a risk that the emission control standards may not be met.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-KFKH5H	KANGOO	2023	20
		TOTAL	20