VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-4003	DATE	May. 19th, 2024	
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)			
DESCRIPTION OF DEFECT	Due to a software bug in the variable valve control (Valvetronic) software diagnostic information of the OBD system will get lost in case of certain diagnostic trouble codes. If a Valvetronic malfunction is permanent present, the limp home mode is activated. If there is another malfunction of an emission related part (e.g oxygen sensor) at the same time or after Valvetronic software freeze, diagnostic information of another part malfunction will also get lost, and increased emission are possible without MLI illumination.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
7AA-42EM	XB7	2023-2025	4
		TOTAL	4