

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3996	DATE	May. 15. 2025
MANUFACTURER	Honda Cars India Ltd. Honda Motor Co., Ltd.		
DESCRIPTION OF DEFECT	An inappropriate leather material has been selected for the interior material of the right side of the driver's seat back and the left side of the front passenger's seat back, which causes fire to spread faster than specified by safety standards during a burning test, making the material not compliant with the standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
5BA-DG5	「WR-V」	2024～2025	4,669	X TYPE
			TOTAL	4,669