

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-3969	DATE	08.05.2025
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to a software bug in the variable valve control (Valvetronic) software diagnostic information of the OBD system will get lost in case of certain diagnostic trouble codes. If a Valvetronic malfunction is permanent present, the limp home mode is activated. If there is another malfunction of an emission related part (e.g oxygen sensor) at the same time or after Valvetronic software freeze, diagnostic information of another part malfunction will also get lost, and increased emission are possible without MLI illumination.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-32EU44A	「BMW X5 M60i xDrive」	2022 - 2023	14
3AA-12ET44	「BMW X5M Competition」	2023	4
3AA-42EX44	「BMW X6 M60i xDrive」	2022 - 2023	13
3AA-12ET44	「BMW X6M Competition」	2023	5
3AA-32EM44	「BMW X7 M60i xDrive」	2022 - 2024	57
3LA-22CS44	「BMW XM LABEL」	2023	7
3LA-22CS44	「BMW XM」	2022-2023	75
		TOTAL	175