

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI 3993	DATE	May 7, 2025
MANUFACTURE	SCANIA CV AB (Japanese Importer: SCANIA JAPANA Co. Ltd.)		
DESCRIPTION OF DEFECT	<p>Some trailer air hoses used when connecting to a trailer are not strong enough due to improper manufacturing processes.</p> <p>As a result, if the service circuit (yellow hose) is damaged by driving vibration or other causes, a warning light will illuminate, air will not be supplied to the trailer side, and the trailer may lose braking power completely.</p> <p>In addition, if the emergency circuit (red hose) is damaged by driving vibration, etc., air is not supplied to the trailer side, the trailer is braked, and in the worst case, a fire may occur if the trailer continues to be used as is.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	LPGRS series Truck	2022-2024	794
		TOTAL	794