

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~X~~ Import Vehicles

CAMPAIGN No.	Gai-4031	DATE	2025/6/26
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan G.K.)		
DESCRIPTION OF DEFECT	<p>On certain G-Class (465 platform) vehicles, the warning messages of the ESP control unit might not meet the requirements.</p> <p>In the event of an independent hardware failure of the ESP system, certain functions of the system (e.g. ESP, ABS, recuperation) would be deactivated as specified. Although the driver would be made aware of the issue by warning messages, the displayed warnings might not be as specified. Furthermore, the malfunction indicator light might not be activated as intended in case of a deactivated recuperation system.</p> <p>Consequently, local legal requirements might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-465310C	G 450 d	2024	604
7CA-465310C		2025	1,185
ZAA-465600C	G 580	2024	956
		2025	93
	Mercedes-AMG G 63	2024	268
4AA-465250C		2025	1,084
		2025	578
		TOTAL	4,768