

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

| | | | |
|-----------------------|---|------|-----------------------------|
| CAMPAIGN No. | Gai-4017 | DATE | 12 th June, 2025 |
| MANUFACTURER | BMW (Japanese Importer: BMW Group Japan Corp.) | | |
| DESCRIPTION OF DEFECT | On affected vehicles one of four screws of the engine mount to frontend connection has been tightened with a torque level lower than required. If the screw has been tightened with lower torque, the screw could be loosened. this may have an influence on the vehicle safety in case of a front crash. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|-----------------------|---------------------|-------------------|
| 3BA-7K15 | BMW 116i | 2023 | 1 |
| | BMW 118i | 2024 | 1 |
| 3BA-7L20 | BMW M235ix Gran Coupe | 2023 | 1 |
| | BMW M135i xDrive | 2023 | 1 |
| | | Total | 4 |