

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3935	DATE	9 th June, 2025
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Blow by liquid may be collected on the intake air hose and drop down on the electrical plug of the coolant pump. Over time this could lead to fluid ingress into the plug and may result in a short circuit or in a worst case in a thermal incident/fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-3B20	「BMW 320i」	2013	1
DBA-3A20	「BMW 328i」	2011-2015	2,619
DBA-3X28	「BMW 328i Gran Turismo」	2013-2016	383
DBA-3N28	「BMW 428i」	2013-2016	498
DBA-4A28	「BMW 428i Gran Coupe」	2014-2016	233
DBA-XG20	「BMW 523i」	2011-2012	2,579
DBA-XL20	「BMW 523i Touring」	2011-2012	945
DBA-XG28	「BMW 528i」	2011-2016	2,644
DBA-XL28	「BMW 528i Touring」	2011-2016	480
DBA-SZ20	「BMW 528i Turismo」	2013-2017	20
DBA-VL20	「BMW X1 sDrive 20i」	2012-2015	1,082
DBA-VM20	「BMW X1 xDrive20i」	2011-2015	4,094
	「BMW X1 xDrive28i」	2011-2015	890
DBA-WX20	「BMW X3 xDrive20i」	2011-2013	1,268

DBA-WX20	「BMW X3 xDrive28i」	2012-2017	600
DBA-XW20	「BMW X4 xDrive28i」	2014-2018	2,049
CLA-KT20	「BMW X5 xDrive40e」	2015-2018	393
DBA-LL20	「BMW Z4 sDrive 20i」	2011-2012	607
		Total	21,385