VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-4006	DATE	5 th June, 2025	
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)			
DESCRIPTION OF DEFECT	Due to the power connector of the starter generator, which may not have been produced correctly there might be a loose connection between the starter generator and B+ terminal of the 48V cable harness. This can lead to a functional impairment and may result in an overheating in the engine compartment. In extremely rare cases an expanding thermal event and or engine stalling without any warning may occur.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-12FJ20	BMW 523i	2023-2024	8
3CA- 22GW20	BMW 523d xDrive Touring	2024	4
3CA- 12GR20	BMW X3 20d xDrive	2024	34
		Total	46