

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-4020	DATE	5 th June, 2025
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	On affected vehicles the 48 V wire to the starter generator might not have been bolted on correctly. In this case, there are contact problems and an increase in the contact resistance in the threaded connection. This may lead to an overheating in the engine compartment. In extremely rare cases an expanding thermal incident and/or engine stalling without any warning may occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-12GR20	BMW X3 20d xDrive	2024	2
3AA-32GP20	BMW X3 20 xDrive	2024	2
		Total	4