

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai—4004	DATE	June 17, 2025
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer: DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	The heat shield tube of the rear brake hose that connects the ABS control unit and the rear brake caliper may not be installed correctly. As a result, the radiant heat emitted from the exhaust pipe close to the brake hose while riding can damage the sheath of the brake hose, and in the worst case, the rear brake may not work.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-5D00	Panigale V4 Panigale V4 S	2025	12
		TOTAL	12