

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4045	DATE	July. 17. 2025
MANUFACTURER	HONDA AUTOMOBILE(THAILAND)CO., LTD. HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for a vehicle equipped with the omnidirectional safety and driver-assistive system, due to the inappropriate control programming of the driver monitoring camera controlling computer, the computer may not finish its arithmetic processing after an external diagnosis system updates the program or clears a failure code. This will keep drawing excessive standby current, and if the vehicle is not used, and parked for a long period of time, the battery will run out, becoming unable to start the power system. After the program is updated by an external diagnosis system, the driver monitoring camera will not start when the power system is started, and the brake warning light and other lights will not turn on at the time of a system failure, which does not meet safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6AA-CY2	「ACCORD」	2025	541
TOTAL			541