

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-4039	DATE	July 14 <sup>th</sup> , 2025
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	On affected vehicles specific cells of the HV Battery may have been mis-aligned due to inappropriate production handling. But there is not lithium plating issue with overhang >0.1mm. The diagnoses function of the Battery Management System of these vehicles would detect a possible short circuit and reduces the SOC status to <30%. Therefore, a thermal propagation is very unlikely to happen. The driver will be informed by a check-control-message.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-82GC32	「MINI Aceman SE」	2024	1
		TOTAL	1