

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4078	DATE	Sep 30, 2025
MANUFACTURE	Aston Martin Lagonda Limited (Japanese Importer : Aston Martin Japan Limited)		
DESCRIPTION OF DEFECT	Due to insufficient design considerations in the control program of the ESP (Electronic Stability Program) module, unnecessary DTCs (trouble codes) may be erroneously detected when the engine is started, causing the brake warning light to come on and the vacuum pump to stop working. As a result, the brake booster cannot be made to create negative pressure, requiring more pedal force than usual, which could result in longer braking distances than the driver anticipated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
NA	Vanquish	2025	29
		TOTAL	29