

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic／Import Vehicles

CAMPAIGN No.	Gai-4068	DATE	September 11, 2025	
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)			
DESCRIPTION OF DEFECT	With regards to BSIS (Blind Spot Information System) which is installed on left side of tractors, due to insufficient examination on adjusting BSIS position to adapt vehicle width standard, the BSIS fixing bolt ends may interfere with fuel tank edge. Thus, if the vehicle continues operation under these conditions, the tank edge may become damaged by vehicle vibration, in the worst case scenario, fuel might leak.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-4S2TDA1	FH	2023-2024	257	
2KG-4S2TEA1 2PG-4S2TEA1		2023-2025	552	
2PG-4S2TGA1		2023-2024	5	
2KG-5S2TDA1 2PG-5S2TDA1		2023-2024	15	
2KG-5S2TEA1 2PG-5S2TEA1		2022-2024	74	
2KG-5S2TGA1 2PG-5S2TGA1		2023-2024	2	
2DG-5S4TBA1 2DG-5S4TBA1改		2022-2024	185	
2DG-5S4TCA1		2023-2024	45	
		TOTAL	1,135	