

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-4060	DATE	September 4 th , 2025
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	On affected vehicles, the routing of the wiper motor wiring harness could be inadequate. As a result, the wiring harness can interfere with the movement of the wiper linkage, leading to damage of the harness. This may result in the malfunction of the wiper, the illumination of the warning light or a short circuit may occur. In this case, a local thermal event within the BCP control unit, which may also lead to a smoke development, cannot be ruled out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-12GD15	「MINI Cooper C」	2024	1,660
3BA-22GD20	「MINI Cooper S」	2024	1,107
3BA-42GD15	「MINI Cooper 5 Door C」	2024	1,392
3BA-52GD20	「MINI Cooper 5 Door S」	2024	879
		TOTAL	5,038