

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	GAI-4062	DATE	2025/9/5
MANUFACTURER	Massey Ferguson (Japanese Importer :MSK Farm Machinery Corporation CEO Takahata Toshinobu)		
DESCRIPTION OF DEFECT	The trailer brake of an agricultural tractor sometimes interfered with the fuel tank due to insufficient design study of the compressed air hose. Therefore, if it is used continuously, the compressed air hose is worn out, the pressure of the trailer brake is lost, and the trailer brake does not operate normally. In the worst case, the braking force of the trailer may be lost. We will inspect the relevant compressed air hose of the trailer brake for damage. If the hose is damaged, replace it with a new part and fix it with a bracket. If the relevant compressed air hose is not damaged, use an adapter to extend the hose and fix it with a bracket.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
不明	F728VARIO G7	2023-2024	3
		TOTAL	3