

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	GAI－4064	DATE	2025/9/5
MANUFACTURER	Fendt (Japanese Importer :MSK Farm Machinery Corporation CEO Takahata Toshinobu)		
DESCRIPTION OF DEFECT	It has been found that the software settings in the engine controller are inappropriate. As a result, the exhaust temperature may become excessively high. This could lead to potential damage to the engine. We will reprogram the engine controller with the correct software.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
不明	F930VARIO G6	2020-2021	5
	F933VARIO G6	2020	1
	F936VARIO G6	2020-2022	8
	F942VARIO G6	2020-2021	4
	F930VARIO G7	2022	1
	F933VARIO G7	2022	1
	F936VARIO G7	2022-2023	2
	F942VARIO G7	2022-2024	5
		TOTAL	27