

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-4098	DATE	Oct. 31. 2025
MANUFACTURER	Ford Motor Company		
DESCRIPTION OF DEFECT	<p>SAFETY RECALL: Navigator – Side View Mirror Corrosion –</p> <p>On some of the affected vehicles, the light-emitting diode (LED) logo lamps within the driver side and / or passenger side exterior mirror assemblies may short circuit due to corrosion without tripping the short detection threshold. An electrical short in the exterior mirror increases the risk of fire.</p> <p>Before demonstrating or delivering any new in-stock vehicles involved in this recall, dealers are to disconnect the LED logo lamps per the Technical Instructions. This service must be performed on all affected vehicles at no charge to the vehicle owner.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	Lincoln Navigator	2015 – 2016	44
TOTAL			44