

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4054	Date	October 30, 2025
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to insufficient consideration in the control program of the electromechanical brake servo control unit, when Travel Assist ^(*1) is active and the system detects that the driver has released the steering wheel for a certain period of time, the system may misinterpret a brief braking operation performed by the system as a braking operation by the driver. As a result, Travel Assist may be deactivated. examined, if the driver becomes incapacitated, the system may fail to switch from Travel Assist to Emergency Assist ^(*2) , fail to sound a warning to the driver, and fail to comply with Japanese safety regulation. (*1) Travel Assist: A driver assistance system that supports acceleration, braking, and steering operations. (*2) Emergency Assist: An emergency stop assistance system that automatically brings the vehicle to a safe stop when the driver becomes incapacitated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-CJ15V	Passat 1.5 TSI	2025	625
3LA-CJ15V	Passat GTE	2025	227
3DA-CJ20V	Passat 2.0 TDI	2025	249
3AA-CT15	Tiguan 1.5 TSI	2025	1,588
3DA-CT20	Tiguan 2.0 TDI	2025	866
		Total	3,555