

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-4082	DATE	16 th Oct, 2025
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to the power connector of the starter generator, which may not have been produced correctly there might be a loose connection between the starter generator and B+ terminal of the 48V cable harness. This can lead to a functional impairment and may result in an overheating in the engine compartment. In extremely rare cases an expanding thermal event and or engine stalling without any warning may occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-12GR20	BMW X3 20d xDrive	2024-2025	8
		Total	8