

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-4092	DATE	October 16, 2025
MANUFACTURE	Bentley Motors Limited (Japanese Importer : Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to a process error at the production, the bolted joint connection securing the high-pressure fuel pump to the engine may not have been tightened to the correct torque specification. The high-pressure fuel pump is not fastened to the engine correctly, the fuel pump could work loose and suffer internal damage, which in the worst case could lead to a fuel leak. A fuel leak, in the presence of an ignition source, can increase the risk of a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7LA-3S40B	Flying Spur V8 PHEV	2025	1
7LA-3S40C	Continental GT V8 PHEV	2025	1
		TOTAL	2