

第 3 号様式（英文リコール概要書）（第 2 関係）

TIRE SAFETY RECALL CAMPAIGN IN JAPAN				
Domestic Tires				
CAMPAIGN No.	Sou- 1 9	DATE	As soon as it's ready	
MANUFACTURER	THE YOKOHAMA RUBBER CO., LTD.			
DESCRIPTION OF DEFECT	Tire (Possible air leakage from a sidewall) Due to improper manufacturing instructions, some of the subject tires may not have been manufactured with a proper material placement at the upper sidewall of the tire. Improper material placement may got the cracks, and if undetected or ignored, the continued loss of air may make impossible to drive. The tires of the subject Serial will be inspected, and the corresponding tires will be replaced with good ones.			
COMMERCIAL NAME	TYPE	CLASSIFICATION	MODEL YEAR RECALLED	NUMBER OF ITEMS
126S	385/55 R22.5 158L	For TRUCK	FB VH YYY 0123 ~ 3925 Jan. 1st, 2023 ~ Oct. 4th, 2025	16
			Total	16