

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	gai - 4119	DATE	December 12, 2025
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer: DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	Due to insufficient strength analysis of the rear axle, excessive stress may occur at the notched section. As a result, cracks may develop in the rear axle during riding, causing abnormal noise, and in the worst case, the rear axle may fracture, leading to a risk of the motorcycle overturning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-DA00J	Panigale V4 Panigale V4 S Panigale V4 Speciale Panigale V4 25 ° Anniversario 916 Panigale V4 FL Panigale V4 S FL	2018 2019 2020	862
2BL-DA04	Panigale V4 R	2019 2020	153
2BL-FA00	Streetfighter V4 Streetfighter V4 S	2020	287
2BL-DC00	Superleggera V4	2020 2021	28
2BL-1F00	Streetfighter V4 Streetfighter V4 S Streetfighter V4 SP	2021 2022	440
2BL-1D00	Panigale V4 Panigale V4 S Panigale V4 SP	2021	215
2BL-3D00	Panigale V4 Panigale V4 S	2022	63
8BL-3D00	Panigale V4 Panigale V4 S Panigale V4 SP2 Panigale V4 2022 WCR Panigale V4 2023 Replica	2022 2023 2024	271

8BL-3D06	Panigale V4 R	2023 2024	194
8BL-4F00	Streetfighter V4 Streetfighter V4 S Streetfighter V4 SP2 Streetfighter V4 Lamborghini	2023 2024 2025	309
		TOTAL	2822