

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-4126	DATE	11-Dec-25
MANUFACTURER	JOHN DEERE (Japanese importer:YANMAR AGRIBUSINESS CO.,LTD.)		
DESCRIPTION OF DEFECT	In the hydraulic circuit of agricultural tractors, a certain hydraulic hose that form part of the brake supply line may have insufficient crimp strength due to improper crimping during assembly. Therefore, Continued use under these conditions may result in hydraulic fluid leakage and, in the worst-case scenario, could lead to brake failure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
—	JD-7R250	2022	2	
—	JD-7R290	2022	1	
—	JD-7R310	2022~2023	2	
—	JD-7R330	2020~2022	4	
—	JD-7R350	2021~2024	17	
TOTAL			26	