

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-4115	DATE	December 04, 2025
MANUFACTURE	FCA US LLC (Japanese Importer : Stellantis Japan Ltd. )		
DESCRIPTION OF DEFECT	During some Battery Pack Control Module (BPCM) resets, the Hybrid Control Processor (HCP) incorrectly interprets a signal from the BPCM. A BPCM reset which is incorrectly interpreted by the HCP may cause a loss of propulsion.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-WL20	「Grand Cherokee」	2023	231
3LA-WL20A	「Grand Cherokee」	2023	355
7LA-WL20A	「Grand Cherokee」	2022	1
		TOTAL	587