

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic & Import Vehicles

CAMPAIGN No.	Gai-4072	DATE	1.12.2025
MANUFACTURE	Ferrari SpA (Japanese Importer: Ferrari Japan K.K.)		
DESCRIPTION OF DEFECT	Regarding the internal circuit for the rear door external opening switch system, due to potential water infiltration in rare instances attributable to process variability in the sealant application on the switch assembly, the circuit may deteriorate, resulting in malfunctions of the external opening system. In some cases, a malfunction of the external rear door handle, such as the rear door not opening from the outside, could occur. In the worst-case scenario, a sudden opening of the rear doors may occur, provided they are not locked, while the vehicle is stopped or moving at a speed lower than 4 km/h.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-F175AHA	Purosangue	MY2023 - MY2024	257 cars
		TOTAL	257 cars